



State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070011
Inspection Type:	COMPLETE
Inspection Date:	Thursday, October 02, 2008
Start Date/Time:	10/2/2008 8:30:00 AM
End Date/Time:	10/2/2008 11:30:00 AM
Last Inspection:	Tuesday, September 02, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 70 Deg. F. InspectionID Report Number: 1787

Accepted by: jhelfric

10/7/2008

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC Site: HIAWATHA MINE COMPLEX

Address: PO BOX 1245, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	12,177.00
Total Disturbed	290.00
Phase I	
Phase II	
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State ☐ Surface Loadout County Processing Fee Other □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Shawn Baker from the company was present during the inspection.

ı	ns	ped	ctor	's	Sia	natu	ıre:

Karl Houskeeper, Environmental Scientist III

Date

Thursday, October 02, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070011 Inspection Type: COMPLETE

Inspection Date: Thursday, October 02, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		✓	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	V			
13.	Revegetation	V			
14.	Subsidence Control	V			
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	V			
20.	Air Quality Permit	V			
21.	Bonding and Insurance	V		~	
22.	Other	V			

Permit Number: C0070011 Inspection Type: COMPLETE

Inspection Date: Thursday, October 02, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/0011 was issued effective 03/14/2007 and expires 03/14/2012.

- -Certificate of Insurance policy number APP158017202, issued 03/03/2008 and terminates 03/03/2009.
- -UPDES permit # UT0023094 effective 09/24/2004 and expires @ midnight 09/23/2009.
- -Air Quality permit BAQE-502-89, issued July 25, 1989.
- -SPCC Plan dated 02/14/06. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The ID signs contained the necessary information.

4.a Hydrologic Balance: Diversions

Multiple diversions in the middle fork portion and around the refuse pile are in need of maintenance work. The operator agree to have the needed work accomplished before the next inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment ponds were last inspected on 09/30/2008.

4.d Hydrologic Balance: Water Monitoring

Second quarter 2008 water monitoring is in the EDI website and uploaded.

7. Coal Mine Waste, Refuse Piles, Impoundments

The last refuse pile inspection was done on 09/30/2008. No problems were noted.

21. Bonding and Insurance

Letter of credit Bank One of Utah for \$2,838,000.